Franklin J. Rooks Jr., Esq. PA Attorney ID: 309562 Jared A. Jacobson, Esq. PA Attorney ID: 201382 Jacobson & Rooks, LLC 525 Route 73 North Suite 104 Marlton, NJ 08053 (856) 874-8999 (856) 494-1707fax

v.

Attorneys for Plaintiff

# IN THE UNITED STATES DISTRICT COURT FOR THE EASTERN DISTRICT OF PENNSYLVANIA

GEORGE GOODRITZ : No.

Plaintiff,

ADR 18<sup>TH</sup> & SANSOM, LLC

and:

INTERPARK, LLC : COMPLAINT

:

Defendants:

# **PRELIMINARY STATEMENT**

George Goodritz (the "Plaintiff"), by and through his counsel, brings this lawsuit against ADR 18<sup>th</sup> & Sansom, LLC, and Interpark, LLC seeking all available relief under the Americans with Disabilities Act for the failure to comply with the Act's accessibility requirements. Plaintiff is seeking injunctive relief requiring the Defendants to remove the accessibility barriers which exist at their parking facility. The allegations contained herein are based on personal experience of the Plaintiff.

# I. JURISDICTION

- 1. This action is brought pursuant to the Americans with Disabilities Act of 1990 ("ADA"), 42 U.S.C. § 12101 et seq.
- 2. This civil controversy arises under the laws of the United States, and jurisdiction in conferred upon this District Court, pursuant to 28 U.S.C. §1331.

# II. VENUE

- All actions complained of herein took place within the jurisdiction of the United States
   District Court for the Eastern District of Pennsylvania.
- 4. Venue is proper in this judicial District as provided by 28 U.S.C. §1391(b).

# III. PARTIES

- 5. Plaintiff is a 69 year-old adult male who currently resides in the Commonwealth of Pennsylvania.
- 6. Plaintiff is a disabled individual.
- 7. The Philadelphia Board of Revision of Taxes lists ADR 18<sup>th</sup> & Sansom, LLC ("Defendant ADR"). as the owner of 1728 Sansom Street, Philadelphia, Pennsylvania 19103, having a tax account number of 883420000.
- 8. According to the Pennsylvania Department of State, Defendant ADR is a domestic limited liability company with an entity identification number of 3156944.
- Defendant ADR has a business address of 1845 Walnut Street, Suite 2200,
   Philadelphia, Pennsylvania 19103.
- 10. Interpark, LLC ("Defendant Interpark") is a foreign limited liability company registered with the Pennsylvania Department of State under entity identification number 4058598.

- 11. The Corporation Service Company is listed as the registered agent for Defendant Interpark at a business address of 2595 Interstate Drive Suite 103, Harrisburg, Pennsylvania 17110.
- 12. Defendant ADR and Defendant Interpark are collectively referred to herein as the "Defendants."

# IV. STATEMENT OF FACTS

# The Parking Facility

- 13. Defendant ADR owns a public parking garage located at 1728 Sansom Street, Philadelphia, Pennsylvania 19103 (the "Parking Facility").
- 14. Upon information and belief, Defendant Interpark manages the Parking Facility for Defendant ADR.
- 15. The Parking Facility offers parking to the general public.
- 16. For a fee, an individual can park a vehicle in the Parking Facility at the prevailing market rates.
- 17. The Parking Facility has multiple parking levels.
- 18. The Parking Facility has in excess of 100 (one-hundred) parking spaces.
- 19. The Parking Facility is a valet-only parking garage.
- 20. The entrance to the Parking Facility is located on Sansom Street.
- 21. There are 2 (two) lanes to enter the parking garage.
- 22. There is 1 (one) lane to exit the parking garage.
- 23. None of the 3 (three) lanes have any marked access aisles that are outside of the vehicular traffic area. (See Exhibit A)

- 24. None of the 3 (three) lanes have any areas which are marked for passenger loading or unloading.
- 25. Upon entering the Parking Facility, the customer must exit his or her vehicle to allow the parking attendant to park the vehicle.
- 26. A parking attendant gives a ticket to each customer.
- 27. Prior to leaving the Parking Facility, the customer must use the ticket to pay at a kiosk located inside a room to the right of western-most entrance lane. (See Exhibit B)
- 28. The room where the payment kiosk is located is separated from the parking garage area by a door; the door opens inwards into the room where the payment kiosk is located.
- 29. There is a raised threshold that is greater than 1 (one) inch in height which must be crossed to enter into the room where the payment kiosk is located.
- 30. The door has a door knob which the must be rotated in order to open the door.
- 31. The room in which the payment kiosk is located does not have an unobstructed 36-inch by 36-inch floor space area in from of the payment kiosk.

## *The Plaintiff*

- 32. The Plaintiff is a disabled individual within the meaning of the ADA.
- 33. The Plaintiff has difficulty walking.
- 34. The Plaintiff possesses a handicap parking placard issued by the Commonwealth of Pennsylvania.
- 35. The Plaintiff's handicap parking placard permits him to park his vehicle in spaces designated as being handicap-accessible.
- 36. The Plaintiff's personal vehicle is a 2016 Toyota RAV 4.

- 37. The Plaintiff travels to Philadelphia frequently, and is often unable to find parking on the streets.
- 38. Plaintiff parks in a parking garage or parking lot when on-street parking is not available.
- 39. The Plaintiff has previously patronized the Parking Facility.
- 40. The Plaintiff would patronize the Parking Facility in the future, but is currently deterred because of the lack of any handicap-accessible loading zones.

# THE AMERICANS WITH DISABILITIES ACT

- 41. Congress enacted the Americans with Disabilities Act ("ADA") in 1990 with the purpose of providing "[a] clear and comprehensive national mandate for the elimination of discrimination against individuals with disabilities" and "[c]lear, strong, consistent, enforceable standards addressing discrimination against individuals with disabilities." 42 U.S.C. § 12101(b).
- 42. The ADA provides a private right of action for injunctive relief to "any person who is being subject to discrimination on the basis of disability." 42 U.S.C. § 12188(a)(1).
- 43. Under the ADA, a disability is defined as "(A) a physical or mental impairment that substantially limits one or more major life activities of such individual; (B) a record of such an impairment; or (C) being regarded as having such an impairment." 42 U.S.C. § 12102(1).
- 44. Title III of the ADA provides that "[n]o individual shall be discriminated against on the basis of disability in the full and equal enjoyment of the goods, services, facilities, privileges, advantages, or accommodations of any place of public accommodation by any person who owns, leases (or leases to), or operates a place of public accommodation." 42 U.S.C. § 12182.

- 45. "It shall be discriminatory to afford an individual or class of individuals, on the basis of a disability or disabilities of such individual or class, directly, or through contractual, licensing, or other arrangements with the opportunity to participate in or benefit from a good, service, facility, privilege, advantage, or accommodation that is not equal to that afforded to other individuals." 42 U.S.C. § 12182(b)(1)(A)(ii).
- 46. A "public accommodation" are private entities whose operations affect commerce. <u>See</u> 42 U.S.C. § 12181(7).
- 47. In relevant part, Title III requires that the facilities of a public accommodation be "readily accessible to and usable by individuals with disabilities, except where an entity can demonstrate that it is structurally impracticable." 42 U.S.C. § 12183(a)(1).
- 48. Discrimination under the ADA includes the failure to remove architectural barriers where such removal is easily achievable. 42 U.S.C. § 12182(b)(2)(A)(iv).
- 49. "Readily achievable" means easily accomplishable and able to be carried out without much difficulty or expense. 28 C.F.R. § 36.104.
- 50. Under Title III, places of public accommodation and commercial facilities that are newly constructed for occupancy beginning after January 26, 1992, must be "readily accessible to and usable by" individuals with disabilities. 28 C.F.R. § 36.401(a) (1).
- 51. Facility" means all or any portion of buildings, structures, sites, complexes, equipment, rolling stock or other conveyances, roads, walks, passageways, parking lots, or other real or personal property, including the site where the building, property, structure, or equipment is located. 28 C.F.R. § 35.104.
- 52. Existing facilities whose construction predates January 26, 1992, must meet the lesser "barrier removal standard," which requires the removal of barriers wherever it is

- "easily accomplishable and able to be done without undue burden or expense." 28 C.F.R. § 36.304(a).
- 53. March 15, 2012 was the compliance date for using the 2010 ADA Standards for program accessibility and barrier removal.<sup>1</sup>
- 54. Under the ADA, businesses or privately owned facilities that provide goods or services to the public have a continuing obligation to remove accessibility barriers in existing parking lots when it is readily achievable to do so.

# Accessible Parking under the ADA

55. The 1991 implementing rules and the 2010 revisions to the ADA set forth the following requirements for handicap-accessible parking spaces:<sup>2</sup>

Total Number of Parking Spaces Provided in Parking Facility	Minimum Number of Required Accessible Parking Spaces
1 to 25	1
26 to 50	2
51 to 75	3
76 to 100	4
101 to 150	5
151 to 200	6
201 to 300	7
301 to 400	8
401 to 500	9
501 to 1000	2% of the total number of parking spaces
More than 1001	20, plus 1 for each 100 parking spaces over 1000

<sup>&</sup>lt;sup>1</sup> https://www.ada.gov/2010ADAstandards\_index.htm

<sup>&</sup>lt;sup>2</sup> https://www.ada.gov/regs2010/2010ADAStandards/2010ADAstandards.htm#pgfId-1010282

- 56. The ADA requires that handicap-accessible parking spaces be at least 96 (ninety-six) inches wide. See Appendix A to Part 36- Standards for Accessible Design, 28 C.F.R. Part 36.<sup>3</sup>
- 57. The width of a parking space is measured from the center of each parking line bordering the parking space.<sup>4</sup> (See Exhibit C)
- 58. The ADA requires that there be an access isle for the handicap-accessible parking space that is at least 60 (sixty) inches wide. (See Exhibit C)
- 59. The 2010 ADA regulations state that one in every six accessible spaces must be van accessible.<sup>5</sup>
- 60. Creating designated accessible handicap spaces is just one example of a barrier removal. 28 C.F.R. § 36.304(b)(18).
- 61. The restriping/repainting of the parking space borders in relatively inexpensive, and should be readily achievable and easily accomplishable.<sup>6</sup>

## Valet Parking

- 62. The 1991 Standards of the ADA and the 2010 Standards of the ADA require parking facilities that provide valet parking services to have an accessible passenger loading zone.<sup>7</sup>
- 63. The 2010 ADA Standards require that valet facilities to also provide accessible parking spaces.<sup>8</sup>

 $<sup>^3</sup>$  https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/ada-standards/chapter-5-general-site-and-building-elements

<sup>&</sup>lt;sup>4</sup> Id.

 $<sup>^{5}</sup>$   $\overline{\text{Id}}$ .

<sup>&</sup>lt;sup>6</sup> https://www.ada.gov/restripe.pdf

<sup>&</sup>lt;sup>7</sup> https://www.ada.gov/regs2010/titleIII\_2010/reg3\_2010\_appendix\_b.htm

<sup>8</sup> https://www.ada.gov/regs2010/titleIII\_2010/reg3\_2010\_appendix\_b.htm

- 64. Valet parking facilities must have an accessible passenger loading zone that has an access aisle that is a minimum of 60 (sixty) inches wide and extends the full length of the vehicle pull-up space. (See Exhibit D)
- 65. The 1991 ADA Standards and the 2010 ADA Standards both require a passenger loading zone to have a vehicle pull-up space that is a minimum of 96 (ninety-six) inches wide and a minimum of 20 (twenty) feet in length. (See Exhibit D)
- 66. The passenger loading zone must be located on an accessible route to the entrance of the facility.<sup>10</sup>

# Accessible Routes under the ADA

- 67. Exterior accessible routes may include parking access aisles, curb ramps, crosswalks at vehicular ways, walks, ramps, and lifts.<sup>11</sup>
- 68. This route, which must be at least three feet wide, must remain accessible and not be blocked.<sup>12</sup>
- 69. In parking facilities that do not serve a particular building, accessible parking shall be located on the shortest accessible route of travel to an accessible pedestrian entrance of the parking facility.<sup>13</sup>

<sup>9</sup> https://www.ada.gov/regs2010/titleIII\_2010/reg3\_2010\_appendix\_b.htm

 $<sup>^{10}</sup>$  https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/background/adaag#4.6.6

 $<sup>^{11}</sup>$  https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/background/adaag#3. MISCELLANEOUS

<sup>12</sup> Id.

 $<sup>^{13}\</sup> https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-adastandards/background/adaag#4.3$ 

70. A maximum height of ¾ (three-quarters) of an inch is permitted for existing or altered thresholds if they have a beveled edge on each side with a slope not steeper than 1:2.<sup>14</sup> (See Exhibit E)

## Signage and the ADA

- 71. The ADA standards require the use of the International Symbol of Accessibility (ISA) to identify parking spaces which are reserved for use by individuals with disabilities. (See Exhibit F)
- 72. Handicap-accessible parking spaces must be designed as "reserved" by a showing the ISA.
- 73. The ISA must be used to identify accessible passenger loading zones.
- 74. Directional signage must be used at inaccessible entrances to provide directions to the nearest accessible route.
- 75. Parking space identification signs shall be 60 (sixty) inches minimum above the finish floor or ground surface measured to the bottom of the sign.<sup>16</sup>

# Other Access Issues

- 76. The minimum clear floor or ground space required to accommodate a single, stationary wheelchair and occupant is 30 inches by 48 inches. (See Exhibit G)
- 77. Doorways must provide maneuvering clearances to allow space for a disabled individual to open and proceed through doors, doorways, and gates using wheelchairs and other mobility aids. (See Exhibit H)

<sup>&</sup>lt;sup>14</sup> https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/guide-to-the-ada-standards/chapter-4-entrances,-doors,-and-gates

 $<sup>^{15}\</sup> https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/background/adaag#4.1$ 

https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/ada-standards/chapter-5-general-site-and-building-elements

78. Doors are required to be handicap-accessible. Handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching, or twisting of the wrist to operate. (See Exhibit I)

# COUNT I -

# FAILURE TO PROVIDE A HANDICAP-ACCESSIBLE PASSENGER LOADING AREAS AND ACCESS LANES

- 79. All preceding paragraphs are hereby incorporated by reference as if fully set forth herein.
- 80. The Parking Facility is a public accommodation as defined by ADA.
- 81. The Parking Facility is subject to Title III of the ADA.
- 82. The Plaintiff is a disabled individual within the meaning of the ADA.
- 83. The United States Supreme Court recognized the term "major life activities" includes walking. Bragdon v. Abbott, 524 U.S. 624, 638–39 (1998).
- 84. The major life activity that the constitutes the Plaintiff's disability is his difficulty walking distances.
- 85. The Parking Facility does not have any marked valet-area passenger loading zones.
- 86. The Parking Facility does not have a marked access aisle that is 60 (sixty) inches wide that is adjacent to the vehicle pull-up space for any valet parking.
- 87. The Parking Facility does not have a passenger loading zone with a vehicle pull-up space that is a minimum of 96 (ninety-six) inches wide and a minimum of 20 (twenty) feet in length.
- 88. The Parking Facility does not have any marked accessible routes leading to the outside of the garage.

- 89. The Parking Facility's failure to comply with the parking accessibility requirements of the ADA has created an accessibility barrier for the Plaintiff, and other similarly situated disabled individuals.
- 90. Defendant ADR is responsible for ensuring the Parking Facility's compliance with the ADA.
- 91. Defendant Interpark is responsible for ensuring the Parking Facility's compliance with the ADA.
- 92. The Defendants can remedy their non-compliance with the ADA's parking requirements by creating a marked access aisles and loading zones.
- 93. Compliance with the ADA's parking requirements at the Parking Facility is readily achievable.
- 94. The Defendants' failure to comply with the ADA has denied the Plaintiff the full and equal enjoyment of the parking offered by the Parking Facility.
- 95. The Defendants have discriminated against the Plaintiff by their failure to comply with the ADA.

WHEREFORE, Plaintiff seeks to injunctive relief to require the Defendants to comply with the Americans with Disabilities Act, together with costs and mandatory attorneys' fees under as provided by 42 U.S.C. § 12005, and such other legal and equitable relief from Defendants as the Court deems just and proper.

#### COUNT II –

# FAILURE TO PROVIDE HANDICAP-ACCESSIBLE PARKING SPACES

96. All preceding paragraphs are hereby incorporated by reference as if fully set forth herein.

- 97. Even though the Parking Facility is a valet-only facility, it is still required to have handicap accessible parking spaces.
- 98. The Parking Facility does not have any handicap-accessible parking spaces.
- 99. The Defendants can remedy their non-compliance with the ADA's parking requirements providing handicap-accessible parking spaces for cars.
- 100. The Defendants can remedy their non-compliance with the ADA's parking requirements by providing a van-accessible handicap parking space for vans.

WHEREFORE, Plaintiff seeks to injunctive relief to require the Defendants to comply with the Americans with Disabilities Act, together with costs and mandatory attorneys' fees under as provided by 42 U.S.C. § 12005, and such other legal and equitable relief from Defendant as the Court deems just and proper.

# **COUNT III-**

# FAILURE TO COMPLY WITH THE SIGNAGE REQUIRMENTS UNDER THE ADA

- 101.All of the preceding paragraphs are hereby incorporated by reference as if fully set forth herein.
- 102. The Parking Facility does not have any directional signs for the nearest accessible route.
- 103. The Parking Facility does not have any handicap-accessible parking signs.
- 104. The Parking Facility does not have any van-accessible handicap-accessible parking signs.
- 105. The Parking Facility does not have any marked accessible routes.

- 106. The Defendants can remedy their non-compliance by reallocating existing parking spaces and painting border lines which conform to the dimensional requirements of the ADA for handicap-accessible parking spaces and access aisles.
- 107. The Defendants' failure to comply with the ADA handicap-accessible parking requirements has denied the Plaintiff the full and equal enjoyment of parking offered by the Parking Facility.
- 108. The Defendants have discriminated against the Plaintiff by its failure to comply with the ADA handicap-accessible parking requirements.

WHEREFORE, Plaintiff seeks to injunctive relief to require the Defendants to comply with the Americans with Disabilities Act, together with costs and mandatory attorneys' fees under as provided by 42 U.S.C. § 12005, and such other legal and equitable relief from Defendant as the Court deems just and proper.

# **COUNT IV-**

#### **INACCESSIBLE PAYMENT AREA**

- 109.All of the preceding paragraphs are hereby incorporated by reference as if fully set forth herein.
- 110. The doorknob to the room in which the payment kiosk is located is not handicap accessible.
- 111. The threshold to enter the room where the payment kiosk is located is greater than 3/4 (three quarters) of an inch.
- 112. This raised threshold creates a tripping hazard for the Plaintiff.
- 113. The room in which the payment kiosk is located does not have the proper floor space clearance to allow a wheelchair to maneuver.

114. The room in which the payment kiosk is located does not have the proper floor space

clearance to allow ingress and egress using a wheelchair.

115. The Defendants have discriminated against the Plaintiff by their failure to comply with

the ADA.

WHEREFORE, Plaintiff seeks to injunctive relief to require the Defendants to comply with

the Americans with Disabilities Act, together with costs and mandatory attorneys' fees

under as provided by 42 U.S.C. § 12005, and such other legal and equitable relief from

Defendants as the Court deems just and proper.

Respectfully submitted,

By: FJR5566

Franklin J. Rooks Jr., Esq.

PA Attorney ID: 309562

Jared A. Jacobson, Esq.

PA Attorney ID: 201382

Jacobson & Rooks, LLC

525 Route 73 North

Suite 104

Marlton, NJ 08053

(856) 874-8999

(856) 494-1707fax

Attorneys for Plaintiff, George Goodritz

Dated: May 25, 2017

# **CERTIFICATE OF SERVICE**

I, Franklin J. Rooks Jr., certify that I served Plaintiff's Complaint via the Court's ECF system.

By: FJR5566

Franklin J. Rooks Jr., Esq.
PA Attorney ID: 309562
Jared A. Jacobson, Esq.
PA Attorney ID: 201382
Jacobson & Rooks, LLC
525 Route 73 North
Suite 104
Marlton, NJ 08053
(856) 874-8999
(856) 494-1707fax
Attorney for Plaintiff, George Goodritz
Dated: May 25, 2017

# EXHIBIT A






EXHIBIT B



# **EXHIBIT C**

Source: <a href="https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/guide-to-the-ada-standards/chapter-5-parking#spaces">https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/guide-to-the-ada-standards/chapter-5-parking#spaces</a>



## **EXHIBIT D**


Source: <a href="https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/guide-to-the-ada-standards/chapter-5-passenger-loading-zones">https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/guide-to-the-ada-standards/chapter-5-passenger-loading-zones</a>

# Vehicle Pull-Up Space (§503.2)

The vehicle pull-up space must be at least 96" wide and at least 20' long.

#### Access Aisle (§503.3)

A marked access aisle is required next to, and at the same level as, the vehicle pull-up space. The access aisle must be at least 60" wide, extend the full length of the vehicle pull-up space, adjoin an accessible route, and cannot overlap vehicular ways. The marking method and color is not specified.



#### Surfaces (§503.4)

Vehicle pull-up spaces and access aisles must meet requirements for ground and floor surfaces (§302) and cannot have changes in level other than slopes not steeper than 1:48. Curb ramps cannot overlap access aisles or vehicle pull-up spaces.

# Vertical Clearance (§503.5)


A vertical clearance of 114" is required at the vehicle pull-up space and access aisle and along a vehicular route connecting them to a vehicle entrance and exit.

Accessible passenger loading zones are not required to be identified by the International Symbol of Accessibility.


# **EXHIBIT E**

 $Source: \underline{https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/guide-to-the-ada-standards/chapter-4-entrances,-doors,-and-gates$ 

# Thresholds [§404.2.5]




The height of thresholds is limited to 1/2" in new construction. The edge must be beveled 1:2 maximum above a height of 1/4". A maximum height of 3/4" is permitted for existing or altered thresholds if they have a beveled edge on each side with a slope not steeper than 1:2. These requirements apply to all types of doors required to comply, including sliding doors.



Note: vertical edge must be located below bevel, not above

# **EXHIBIT F**

# Figure 3B-22. International Symbol of Accessibility Parking Space Marking



Note: Blue background and white border are optional

# **EXHIBIT G**

Source: https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/guide-to-the-ada-standards/chapter-3-clear-floor-or-ground-space-and-turning-space


# Surface and Size [§305.2 and §305.3]


Clear floor spaces must meet requirements for ground and floor surfaces, including criteria for firmness, stability, and slip resistance. They must be free of level changes and not slope more than 1:48.

The minimum size (30" by 48") applies whether the space is positioned for forward or side approaches. Additional space is required when the space is confined on three sides and is obstructed for more than half the depth, such as when elements are recessed in alcoves.

# Approach and Maneuvering Clearance [§305.6] and §305.7]

Where the space is obstructed on both sides for more than half the depth, additional clearance is required for maneuvering. Accessible routes must connect to the unobstructed side of the space.





# **EXHIBIT H**


 $Source: \underline{https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/guide-to-the-ada-standards/chapter-4-entrances,-doors,-and-gates\#ar2065$ 

# Maneuvering Clearances [§404.2.4]

Required maneuvering clearances provide space for opening and proceeding through doors, doorways, and gates using wheelchairs and other mobility aids.



Required door clearances provide unobstructed space for maneuvering through doorways.




Maneuvering clearances must be free of protrusions the full height (80" min.) and changes in level (other than thresholds).

# **EXHIBIT I**

https://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-ada-standards/guide-to-the-ada-standards/chapter-4-entrances,-doors,-and-gates#ar2065'

# Door and Gate Hardware [§404.2.7]



Door and gate hardware must:

- allow one-hand operation
- not require tight grasping, pinching, or twisting of the wrist
- operate with 5 lbs maximum force
- be located 34" to 48" above the floor or ground.

Hardware that can be operated with a loose grip or closed fist, such as lever-shaped handles and U-shaped pulls, accommodates the greatest range of users. (Closed-fist operation, while advisable, is not mandated by the Standards). Round door knobs do not comply because they require twisting of the wrist.

Latches and locks with small parts that must be manipulated can be difficult to use and will not comply if pinching is necessary. However, keys and access cards that are not part of the lockset are not required to comply (but those that do not require pinching or turning provide better access). Hardware that does not require simultaneous actions are better, but some types, such as handles with thumb latches are acceptable